First Presbyterian Church Marion & Lady Sts. Columbia Richland County South Carolina

HABS SC, 40-colum,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS SC 40-COLUM, 12-

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
South Carolina	Richland	Richland Co		
HISTORIC NAME OF STRUCTURE (INCLUOE SOURCE FOR NAME)				HABS NO.
First Presbyterian Church				SC-352
SECONDARY OR COMMON NAM	MES OF STRUCTURE			
COMPLETE ADDRESS (OESCRIE	BE LOCATION FOR RURAL	SITES)		
Marion & Lady Streets				
DATE OF CONSTRUCTION (INCLUOE SOURCE) ARCHITECT(S) (IN			LUOE SOURCE)	
1852-1853				
SIGNIFICANCE (ARCHITECTUR	RAL AND HISTORICAL, INC.	LUOE ORIGINAL USE	OF STRUCTURE)	
Well-preserved Gothic F				
tion of this church inc Association and Dr. & N				nt Vernon Ladies
STYLE (<i>IF APPROPRIATE</i>) Gothic Revival				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				<u> </u>
Stucco on brick				
HAPE AND DIMENSIONS OF ST	TRUCTURE (SKETCHED FL	OOR PLANS ON SEPAF	RATE PAGES ARE A	CCEPTABLE)
Rectangular, one story	with steeple, approx	c. 50' x 100'		
EXTERIOR FEATURES OF NOT				
One tier of windows, co		, tall spire, bu	ttresses, pinna	acles, battle-
mented parapets and gal	bles			
INTERIOR FEATURES OF NOTE	E (OESCRIBE FLOOR PLANS	S, IF NOT SKETCHEO)	<u> </u>	
				00 10 12 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15
MAJOR ALTERATIONS AND AD	DDITIONS WITH DATES		:	
1875 damaged by stor	cm; 1925 restored			
PRESENT CONDITION AND USE				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (I		*	44,	
Outh Carolina Writers' Oxford University Press			the Palmetto	State, (New York:
	-, -/, -/, -/ 200			
COMPILER, AFFILIATION			DATI	
	Melissa McDonald	HABS Historian		8 - 8-83